

APC Techsafe is a 3M Authorized Service Centre providing inspection, repairs and servicing of Sala and Protecta fall arrest blocks, SRL's and retrieval winches. Our workshop is fully equipped and staffed by our team of factory trained technicians who use only genuine parts and tooling.

SERVICE PROCEDURE:

- Units are booked into a service database with full history logged
- Units are put through a pre-service inspection to gauge scope of repairs
- All units are dismantled completely and cleaned
- Mandatory parts are installed following manufacturer's instructions

- Components are checked for wear, corrosion or other damage and replaced as needed
- The critical energy absorbing brake element is re-calibrated to ensure performance
- Entire unit is assembled and post-service inspection performed
- Certification is issued for each completed unit

Examples of SRL's and winches that can be serviced by APC Techsafe:







REBEL RANGE

(6-30m models)



ULTRA-LOK RANGE



SALA SEALED RANGE

(33-85ft models)



SALALIFT II



DIGITAL WINCH



EZ-LINE

CODE	DESCRIPTION	PRICE
482761	Service Charge SRL	\$300.00
482762	Service Charge SRL With Retrieval/Rescue Function	\$400.00
482763	Service Charge Winch	\$500.00

Note: All pricing excludes freight and GST and is subject to change. Valid from December 2019. Pricing includes the annual service and installation of mandatory parts only. Parts replaced due to wear and/or damage will be at additional cost and quoted prior to repair. An investigation fee of \$100.00 may be applicable if repairs are not approved.

We don't just sell safety equipment. We make sure you know how to use and maintain it correctly.





TRAIN



WORKSAFE TRAINING
BY NZ SAFETY BLACKWOODS