## NZSafetyBlackwoods TECHNICAL SOLUTIONS

# HEIGHT & RESPIRATORY EQUIPMENT INSPECTION & SERVICE

APC Techsafe provide a complete inspection and repair service for height safety equipment. APC Techsafe's workshop is fully equipped with the latest equipment and staffed by our team of highly experienced, factory trained and registered technicians.

### **SERVICES INCLUDE:**

- Inspection of harnesses, hardware, lanyards, ropes and more
- 3M block servicing
- Respiratory equipment servicing

## RETURN EQUIPMENT FOR SERVICE TO:

APC Techsafe 660 Rosebank Road Avondale, Auckland, 1026

#### PHONE: 0800 832 732

Please ensure you provide a purchase order, return address and brief description of work required.

#### **HEIGHT SAFETY:**

Description	Code	Ex GST
Inspection Basic Harness	482431	\$50.00
Inspection Hardware	482433	\$25.00
Inspection Lanyard	482434	\$40.00
Inspection Temporary Lifeline	482435	\$80.00
Inspection Recovery System [RPD]	482436	\$120.00
Inspection Tripod	482437	\$150.00
Inspection Rope Per Metre (If it has valid supplier label & details for tracking)	482438	\$2.50

#### **RESPIRATORY:**

Description	Code	<b>Ex GST</b>
Service Charge Proflow	481741	\$170.00
Service Charge Compressed Airline Purifier	482440	\$120.00
Service Charge Powered Airline Purifier	482443	\$65.00

Note: All pricing excludes freight and GST and is subject to change. Valid from 1 December 2019.

